

DBB ROV Services A/S



List of References

2015

Maersk Oil & Gas A/S

Drill Support, Visual Inspection Survey, Close Visual Inspection Survey, General Survey, UWILD Survey – 350 bar Hydro Jet cleaning of welds for close visual inspection. Spud can penetration checks and scour surveys on the following rigs:

Noble Sam turner

Ensco 71

Ensco 72

Energy Enhancer

Atlantic Labrador

Seafox 5

Rigmar

COSL Haven

Maersk Resilient

DONG/Hess:

2x South Arne SAL System, inspection surveys. O/B Esvagt Omega.

5x RSU-Mærsk Resolute, Drillsupport & Spud can Inspection surveys.

2014

Vattenfall:

HornsRev- Monopile Cutting, O/B Jack-up Wind.

DONG-Hess:

South Arne SAL System surveys

Maersk Resolute, drill support and spud can surveys

DONG:

Nysted wind farm,

Cutting monopoles with wire cutter

Maersk Oil & Gas A/S

Drill Support, Visual Inspection Survey, Close Visual Inspection Survey, General Survey, Spud can penetration checks and scour surveys and salvage of various items on the following rigs:

Atlantic Labrador

Ensco 71

Ensco 72

Noble Sam Turner

Seabed Wave Energy – Kungshamn, Sweden:

Positioning and establishing of several wave energy machines.

E.on, Amrumbank West, Helgoland:

Mounting lines for cable pulling into the monopoles – seabed and scour surveys. MS-lines.
From M/V-LINA & M/V-Carrier.

2013

Maersk Oil & Gas A/S:

Ensco 72, Seabed survey, Conductor guidance, Drill support, Spud can scour inspection surveys.

DONG- Hess:

Hess Phase 3 Drilling Campaign, SAN 04.

South Arne SAL System, Inspection surveys

RSU- Mærsk Resolute, Drillsupport, Conductor guidance, Spudcan Inspection Surveys. Gas & Bobbles watch.

Dansk Tysk Windmill park (Helgoland)

UXO surveys, Tracking system,

Hydraulic suction system, NaviPac.

Fred Olsen Windcarrier:

Jack up "Brave Tern"

Bucket Met mast installations on the Dogger Bank.

DONG:

Cutting Met masts at Nysted Wind mill park

2012

Maersk Oil & Gas A/S:

Drill Support, Conductor guidance, Visual Survey, Close Visual Survey, General Survey, Spud can penetration checks and scour surveys and salvage of various items on the following rigs:

Ensco 71

Ensco 72

Atlantic Labrador

GSF Monarch

Maersk Endeavour

Maersk Resolute

Maersk Resolve

Noreco

The Luna 1X drilling

Nordstream – Saipem:

Nordstream / Saipem pipeline Pig tracking, Baltic sea / Gulf of Finland.

DONG:

Noise reduction measurements at Anholt wind farm. Placing and orientation of noise measurement systems.

Moyle investigation:

Nordic Offshore, Search for cable fault, video inspections, dive support for Osiris divers.

2011

Vestas A/S:

MS 1071 High Resolution Scanning of windmill foundations and surrounding areas.

Maersk Oil & Gas A/S

Drill Support, Conductor guidance, Visual Survey, Close Visual Survey, General Survey, Spud can penetration checks and scour surveys and salvage of various items on the following rigs:

Ensco 71

Energy Endeavour

GSF Monarch

Atlantic Labrador

DBB Salvage A/S:

Survey of grounding / hull inspection.

2010

Maersk Oil A/S:

Drill Support, Conductor guidance, Visual Survey, Close Visual Survey, General Survey, Spud can penetration checks and scour surveys and salvage of various items on the following rigs:

Ensco 70

Ensco 72

Maersk Reacher

Maersk Resolve

DBB Salvage: (Fu Shan Hai)

Survey of oil leak from "Fu Shan Hai"

Robin Rigg:

Gear box replacements in the windmill park "Robin Rigg" monitoring the development of scour under the spud cans in tides running up to 6 knots.

References earliere than 2010

Mærsk Rig: Safe Esbjerg, Salvage of seawaterpump, using Hydro Lek5 Function manip. & wires.

Spudcan Inspection Surveys on rigs: Ensco 101, Ensco 71, Atlantic Rotterdam.

Windfarm Alpha Ventus, Inspection Surveys of monopoles, Tripods & overflow control. O/B Jackup Barge ODIN.

DONG: Siri-SAL system, North sea. O/B Esvagt Gamma

Rig: Noble Baron, Conductor Guidance

Mærsk Oil & Gas: Regnar Bouy, Leak Investigation Survey.northsea

Inner Dowsing Windfarm, Grimsby. Sonar scans inside monopoles.

Mærsk Rig: Energy Enhancer, Inspection of legs, water Intakes & Spudcan Inspection Survey.

Carried out Spudcan Inspection Surveys, Debris Survey, Drill support, Conductor guidance on Rigs offshore:

Energy Enhancer, Energy Endesver, Energy Exerter, Ensco 71 & Ensco 101.