

# **DBB ROV Services A/S**



## **List of References**

## **2015**

### **Maersk Oil & Gas A/S**

Drill Support, Visual Inspection Survey, Close Visual Inspection Survey, General Survey, UWILD Survey – 350 bar Hydro Jet cleaning of welds for close visual inspection. Spud can penetration checks and scour surveys on the following rigs:

Noble Sam turner

Ensco 71

Ensco 72

Energy Enhancer

Atlantic Labrador

Seafox 5

Rigmar

COSL Haven

Maersk Resilient

### **DONG/Hess:**

2x South Arne SAL System, inspection surveys. O/B Esvagt Omega.

5x RSU-Mærsk Resolute, Drillsupport & Spud can Inspection surveys.

## **2014**

### **Vattenfall:**

HornsRev- Monopile Cutting, O/B Jack-up Wind.

### **DONG-Hess:**

South Arne SAL System surveys

Maersk Resolute, drill support and spud can surveys

### **DONG:**

Nysted wind farm,

Cutting monopoles with wire cutter

## **Maersk Oil & Gas A/S**

Drill Support, Visual Inspection Survey, Close Visual Inspection Survey, General Survey, Spud can penetration checks and scour surveys and salvage of various items on the following rigs:

Atlantic Labrador

Ensco 71

Ensco 72

Noble Sam Turner

## **Seabed Wave Energy – Kungshamn, Sweden:**

Positioning and establishing of several wave energy machines.

## **E.on, Amrumbank West, Helgoland:**

Mounting lines for cable pulling into the monopoles – seabed and scour surveys. MS-lines.  
From M/V-LINA & M/V-Carrier.

## **2013**

### **Maersk Oil & Gas A/S:**

Ensco 72, Seabed survey, Conductor guidance, Drill support, Spud can scour inspection surveys.

### **DONG- Hess:**

Hess Phase 3 Drilling Campaign, SAN 04.

South Arne SAL System, Inspection surveys

RSU- Mærsk Resolute, Drillsupport, Conductor guidance, Spudcan Inspection Surveys. Gas & Bobbles watch.

Dansk Tysk Windmill park (Helgoland)

UXO surveys, Tracking system,

Hydraulic suction system, NaviPac.

**Fred Olsen Windcarrier:**

Jack up "Brave Tern"

Bucket Met mast installations on the Dogger Bank.

**DONG:**

Cutting Met masts at Nysted Wind mill park

**2012**

**Maersk Oil & Gas A/S:**

Drill Support, Conductor guidance, Visual Survey, Close Visual Survey, General Survey, Spud can penetration checks and scour surveys and salvage of various items on the following rigs:

Ensco 71

Ensco 72

Atlantic Labrador

GSF Monarch

Maersk Endeavour

Maersk Resolute

Maersk Resolve

**Noreco**

The Luna 1X drilling

**Nordstream – Saipem:**

Nordstream / Saipem pipeline Pig tracking, Baltic sea / Gulf of Finland.

**DONG:**

Noise reduction measurements at Anholt wind farm. Placing and orientation of noise measurement systems.

Moyle investigation:

Nordic Offshore, Search for cable fault, video inspections, dive support for Osiris divers.

## **2011**

### **Vestas A/S:**

MS 1071 High Resolution Scanning of windmill foundations and surrounding areas.

### **Maersk Oil & Gas A/S**

Drill Support, Conductor guidance, Visual Survey, Close Visual Survey, General Survey, Spud can penetration checks and scour surveys and salvage of various items on the following rigs:

Ensco 71

Energy Endeavour

GSF Monarch

Atlantic Labrador

### **DBB Salvage A/S:**

Survey of grounding / hull inspection.

## **2010**

### **Maersk Oil A/S:**

Drill Support, Conductor guidance, Visual Survey, Close Visual Survey, General Survey, Spud can penetration checks and scour surveys and salvage of various items on the following rigs:

Ensco 70

Ensco 72

Maersk Reacher

Maersk Resolve

### **DBB Salvage: (Fu Shan Hai)**

Survey of oil leak from "Fu Shan Hai"

### **Robin Rigg:**

Gear box replacements in the windmill park "Robin Rigg" monitoring the development of scour under the spud cans in tides running up to 6 knots.

### **References earliere than 2010**

Mærsk Rig: Safe Esbjerg, Salvage of seawaterpump, using Hydro Lek5 Function manip. & wires.

Spudcan Inspection Surveys on rigs: Ensco 101, Ensco 71, Atlantic Rotterdam.

Windfarm Alpha Ventus, Inspection Surveys of monopoles, Tripods & overflow control. O/B Jackup Barge ODIN.

DONG: Siri-SAL system, North sea. O/B Esvagt Gamma

Rig: Noble Baron, Conductor Guidance

Mærsk Oil & Gas: Regnar Bouy, Leak Investigation Survey.northsea

Inner Dowsing Windfarm, Grimsby. Sonar scans inside monopoles.

Mærsk Rig: Energy Enhancer, Inspection of legs, water Intakes & Spudcan Inspection Survey.

Carried out Spudcan Inspection Surveys, Debris Survey, Drill support, Conductor guidance on Rigs offshore:

Energy Enhancer, Energy Endesver, Energy Exerter, Ensco 71 & Ensco 101.